

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- ① FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- ① BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**






Figure Three (3) A.
Close-up photo of an installed Headrest and Screen Cover
Application Number 10/724,439



Figure Three (3) B.
Installed Headrest and Screen Cover with rear panel partially removed.
Application Number 10/724,439




Figure Three (3) C.
Installed Headrest and Screen Cover with the rear panel removed.
Application Number 10/724,439

Figure Number One: Drawing of the Headrest and Screen Cover

